



Communication between Robot with Sensor system

1. Dedicated Method

1) Basic

```

Robot -----> Sensor System
  SREQ R=1, PT=1
or SREQT R=1, PT=1, WT=10.0, SS=100
  R1.CFG = Port No×2 (set Request bit)
  -----> "SHIFT 1[CR][LF]"
  <----- "SHIFT 10, 20, 30, 0, 0[CR]"
  R1.CFG = &B10000 (set InputState bit,
                    and reset Request )
  R1.X=10, R1.Y=20, R1.Z=30, R1.RX=0, R1.RY=0, R1.Z=0
  SONL ST=1, RF=0, R=1, SS=10
  Shift next step until SONL ST=0

```

2) expand usage

```

R1=(0, 0, 0, 0, 0, 0)
R1.CFG = Port No×2 (set R1.Reguest = Port No.)
  <----- "SHIFT 10, 20, 30, 0, 0[CR]"
  R1.CFG = &B10000 (set InputState bit,
                    and reset Request )
  R1.X=10, R1.Y=20, R1.Z=30, R1.RX=0, R1.RY=0, R1.Z=0
  IF R1.CFG=&B10000 THEN 10 ELSE 20
  Use R1 element to anywhere in your program.

```

DRAFT

2. ASCII protocol

Refer to Application example.

3. Binary protocol

Robot -----> Sensor System

_TEINPUT=-10 This value is reset at cycle start.

INPUT #1, V1\$

use ORG(V1\$) and MID(V1\$, V1%, 1)

DRAFT

4. Commands about Vision system

① SONL Command

Description	On-line shift (M52)		
Syntax	SONL ST=<Start/End>, RF=<Std>, R=<Register Number>, SS=<Shelter Step No>		
Parameter	Start/End	If 1, starts the shift application. If 0, ends. If 0, all other factors are ignored.	0~1
	Std.	If 0, based on the ground coord. If 1, based on the tool coord.	0~1
	Reg. Number	The register number where the received shift amount is stored.	1~8
	Shelter Step No.	Step to which jump, when the shift amount is not input within the specified time limit.	0~999
Example	SONL ST=1, RF=0, R=1, SS=10		

② SREQ Command

Description	Shift Requirement (M51)		
Syntax	SREQ R=<Register Number>, PT=<Port Number>		
Parameter	Reg. Number	Register number for saving the received shift amount.	1~8
	Port Number	RS232C port number to be used for shift requirement and transmission.	1~1
Example	SREQ R=1, PT=1		

③ SREQT Command

Description	Timer conditional shift function (M56)		
Syntax	SREQT R=<Reg. Number>,PT=<Port Number>,WT=<Wait Time>,SS=<Shelter Step Number>		
Parameter	Reg. Number	Register number for saving the received shift amount.	1~8
	Port Number	RS232C port number to be used for shift requirement and shift amount transmission.	1~1
	Wait Time	wait time until receiving the shift amount.	0.0~60.0 (sec)
	Shelter Step Number	Step number to which jumps when the wait time is elapsed.	0~999
Example	SREQT R=1,PT=1,WT=10.0,SS=100		

④ SXYZ Command

Description	XYZ Shift (M58)		
Syntax	SXYZ RF=<Coord>,X=<X Shift Amount>,Y=<Y Shift Amount>,Z=<Z Shift Amount>		
Parameter	Coord.	If 0, ground coord. If 1, tool coord.	0~1
	Shift Amount	Shift Amount to be shifted parallel in 3D.	-3000.0~3000.0
Example	SXYZ RF=0, X=10.50, Y=20.50, Z=0.00		

⑤ TONL1 Command

Description	Online coordinate conversion (Slipping) (M53)		
Syntax	TONL1 ST=<Start/End>,RF1=<Ref. Step number1>,RF2=<Ref. Step number2>,RF3=<Ref. Step number3>		
Parameter	Start/End	If 1, Coordinate conversion starts. If 0, exits.	0~1
	Ref. Step number	The step numbers used as 3 reference points.	0~999
Example	TONL1 ST=1, RF1=1, RF2=5, RF3=7		

⑥ TONL2 Command

Description	Online coordinate conversion (coordinate value) (M54)		
Syntax	TONL2 ST=<Start/End>, RF1=<Basic Step number1>, RF2=<Basic Step number2>, RF3=<Basic Step number3>		
Parameter	Start/End	If 1, coordinate conversion starts. If 0, exits	0~1
	Ref. Step number	Step numbers used as 3 reference points.	0~999
Example	TONL2 ST=1, RF1=1, RF2=5, RF3=7		

⑦ CLR232C Command

Description	Clears the receive buffer of the serial port (M11)		
Syntax	CLR232C <port no.>		
Parameter	port no.	serial port number	1~2
Example	CLR232C 1		

DRAFT